




1


Carriage on 28 stud base




2





3




4





5





6





7





8




9




10





11





12





13





14




15




16



17



18



12x

2x

4x

2x